

Annexure D

BUILDING SAFETY CERTIFICATE

No. _____

Dated: 7.3.2024

It is certified that the existing building Caramel English School (name of the building or premises) at Kallata, Hiramandalam (mandal) (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	<u>3</u>	<u>3</u>	<u>-</u>	<u>-</u>	<u>-</u>	<u>-</u>

The building is owned/occupied by The Caramel English School (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of R & B Dept. (Name of Department/ Govt.) on 7.3.2024 (date of inspection) in the presence of Executive director Ranjit Kumar Paik (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 7.3.2024 for a period of 01 years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 8.3.2024 at EE(R&B), SriKakulam by _____

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : 

Name : S. RAJINIKANTH

Designation : Executive Engineer (R&B)

Name & Address of Department/ Office : R&B Division, SRIKAKULAM

600
2/5/24

S. Gopala Rao 7.3.2024
Asst. Executive Engineer
(R & B) Section
Pathapatnam